

ERRATA NUMBER:

OCT.-0284

PART NUMBER:

320963

MANUAL AFFECTED:

Commodore Basic Version 4.0, User's Reference Manual. Part #321604, July 1980 Please annotate Appendix H of your basic 4.0 User's Reference Manual to incorporate the following errata items.

1. Page H-2

Change SYS15 address.

<u>Was</u> F198 Should be

Add new system call after SYS28 as follows:

SS29 F198 release attention after talk A

2. Page H-8, top of page:

Was JSR \$F198 Should be JSR \$F0B2

3. Page H-10, item 26:

Was JSR \$F198 Should be JSR \$F0B2

Add the following line before line JSR \$F193:

ORA #\$60

4. Page H-ll, item 27:

Was
Device #8 with ST #15
Device #6 with SA #15

Add the following line before line JSR #F143:

ORA #\$60

5. Page H-ll, item 28

Add new system call after item 28 and before SYS COMMAND as follows:

29. Talk with no secondary address.

This subroutine is called after subroutine #15 if there is no secondary address to be sent.

;Device #8 Talk LDA #8 JSR \$F0B2 JSR \$F198